



**BOSCH**

Robert Bosch (Australia) Pty.  
Ltd  
Locked Bag 66  
Clayton South VIC 3169  
Visitors:  
1555 Centre Road  
Clayton VIC 3168  
Tel +61 3 9541 5555  
www.bosch.com.au

Ben Prior – Supplier Quality Assurance Manager  
Tel +61 (0)3 95415430, Fax +61 (0)3 95441137  
ben.prior@au.bosch.com

1 May 2009

**Dear Ladies and Gentlemen,**

Annual Layout Inspection / Requalification.

According to ISO TS 16949, Chapter 8, Point 2.4.1 all suppliers are required to comply with a layout inspection.

Bosch considers a yearly requalification frequency as suitable. PGQP and control plan characteristics already monitored during supplier manufacturing processes shall be waived from this requirement.

On request access to the results of the annual requalification shall be made available to Bosch. Evidence of conformance may be reviewed during RBAU supplier process audits and supplier visits.

With kind regards,

Ben Prior  
Robert Bosch (Australia)  
Supplier Quality Assurance Manager

ABN 48 004 315 628

BOSCH and the symbol are registered trademarks of Robert Bosch GmbH, Germany

Banking connection: Citibank Pty. Ltd., BSB 242-000 Account No. 201455006 for domestic AUD transactions

Deutsche Bank AG Stuttgart, Swift Code DEUTDESS, Account No. 0165005000 for overseas and foreign currency transactions